

TITLE: Wearing Radiation Dosimeters



Whole Body Dosimeter

Wear the badge on the front of your body between your neck and waist (typically, on your chest), with the label facing toward the source of radiation.

Ring Dosimeter

Wear the finger ring on the hand closest to the radiation source with the label facing the source. Wear the finger ring under your glove to prevent contamination.



Fetal Dosimeter

Wear the badge on the front of your body at your abdominal area, with the label facing toward the source of radiation.

With Lead Garments

Wear the badge near your neck, outside your shielded apron and thyroid shield.

